



View of Argyle Street Bridge over Grand River.



West elevation looking north.



General view of deck from south approach.



General view of sidewalk, railing, expansion joint, and concrete arches.



Concrete arch hanger is in poor condition.



Underside of deck is in poor condition with numerous areas of sprayed concrete repairs on the underside of the deck. Utilities are mounted on the soffit. This is a typical pier profile with boulder/rock rip rap.



Concrete arch beam is in poor condition. Typical diagonal crack at end of main arch beam is clearly visible.



View of load posting sign at the south approach.



Concrete blocks and walkway at south abutment.




Southeast wingwall in fair condition, typical for all wingwalls.



Highway 6 Bypass over Grand River.



Downtown street in Caledonia, looking south.



View of roadway looking north from the bridge.



View of roadway looking south from the bridge.



View of Grand River down stream.



View of Grand River up stream, showing the CN bridge and dam west of the Argyle Street Bridge.



View of the Toll House, at the northeast corner of the bridge.



Toll House heritage plaque, located at the northeast corner of the bridge.



Argyle Street Bridge plaque.



Caledonia Kinsmen Park plaque.